

# General Environmental Incident Summary

**Incident:** 123      **Date/Time Notice:** 7/10/1991      1040      **DEM Incident No:**

**Responsible Party:** Mariner Construction Inc.

**Date Incident:** 6/10/1991      **Time Incident:**      **Duration:**

**County:** Burleigh      **Twp:** 138      **Rng:** 80      **Sec:** 34      **Qtr:** NE

**Lat:** 46.72953      **Long:** -100.76360      **Method:** Derived from TRS

**Location Description:** MISSOURI SLOPE LUTHERN CARE CENTER, 2425 HILLVIEW AVENUE  
BISMARCK

**Submitted By:**

**Affiliation:**

**Address:**

**City:**

**State:**

**Zip:**

**Received By:** Jeff Hauge

**Contact Person:**

**Distance Nearest Occupied Building:**

**Type of Incident:** HYDROCARBON

**Description of Released Contaminant:** Tack Oil

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:**

**Reported to NRC:** No

**Cause of Incident:**

TACK OIL FOR RESURFACING FLOWED INTO A STORMWATER INLET ALONG BOLIVARD AVENUE. MEL FISCHER, CITY OF BISMARCK INSPECTED THE SPILL SITE AND CONTRACTOR WILL WASH DOWN AREA WITH SPECIAL DETERGENT.

**Risk Evaluation:**

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:**

**Potential Environmental Impacts:**

**Action Taken or Planned:**

**Wastes Disposal Location:**

**Agencies Involved:**

